

RS3AB~RS3MB



DATA SHEET

50V~1000V

3.0A SMB




	۱۲۳								

Marking

Type number	Marking code
RS3AB	RS3AB
RS3BB	RS3BB
RS3CB	RS3CB
RS3DB	RS3DB
RS3EB	RS3EB
RS3FB	RS3FB
RS3GB	RS3GB
RS3HB	RS3HB
RS3IB	RS3IB
RS3JB	RS3JB
RS3KB	RS3KB
RS3LB	RS3LB
RS3MB	RS3MB

/ Marking Instructions



RS3A			
****	1 *	3 *	
RS3A			
****	*	*	

šWD t... •Ž¢ (x/) / :KSVKXGZ[XK 6XULORK LUX /8 8KLRU] 9URJKXOTM 6

^a¢y

10•Ä½“† 25½150 - kž• 60½90sec;

20•Q>“† 245 r5 - kž•4 Ò 5 r0.5sec;

30•D N ò i Ò 0 , † 2½10 - /sec.

Note:

1.Preheating:25~150 - , Time:60~90sec.

2.Peak Temp.:245 r5 - , Duration:5 r0.5sec.

3. Cooling Speed: 2~10 - /sec.

ÂD /Cã p ¯ »] / Resistance to Soldering Heat Test Conditions

“†y 260 r5 - ž•y 10 r1 sec.

Temp.:260 r5 -

Time:10 r1 sec

G P á / Packaging SPEC.

2 & x / REEL

Package Type